

## Rebuilt by GPS Reisacher means:



- Recoat of the machine interior
- Rebuilt of the drive motors (with certificate)
- Automatic shut-off for time/temperature/bowl revolutions
- Siemens Elmo water ring vacuum pump (low maintenance)

### Replacement of the following elements:



- Internal switch cabinet
- Power lines and signal lines
- Control panel
- Hydraulic unit
- Hydraulic cylinder
- Hydraulic lines
- Knife shaft
- Central lubrication system
- Lubrication lines
- Seals
- Roller bearings and plain bearings
- Loader
- Emptier disc
- Belt drives
- Sensors and limit switches
- Screw and bolt elements
- Vacuum unit control valves
- External fan for knife shaft motor
- Cladding doors



In the Touch model, most functions are controlled using a touch panel and the overview is more user-friendly.

We only use original GEA spare parts for our machine rebuilding services. The system is compliant with the latest technological standards, which ensures that spare parts are easy to obtain.